

ITH Gnome Stocking



.PES
.DST
.VP3
.JEF
.XXX
.HUS
.EXP

Digital
files

20x30

8x12"

WHAT IS NEEDED:

Padding 1 cm

Foam 1 cm

Felt or fabric of your choice



Before making the sock we make the hood

I put the tear-off stabilizer in the hoop - I embroider the position trace

I put on a square of fabric of about 17x17 cm - I embroider the name

I turn the fabric until I obtain a triangle and embroider the next track

I take off the frame and flip





We make the sock

Hook and loop stabilizer in hoop - Embroider the position mark and the two notches subsequent

I take a 48x20 cm rectangle of fabric, fold it in half and place it in correspondence of the notches, inside I insert the padding

Fixed with pins and embroider the next track



I embroider the next notches

To make the upper part of the sock I take a rectangle of about 18x20 cm

I position it in correspondence with the notches, insert the padding and then fold it back

Fixed with pins. I embroider the next seam and cut out the excess fabric

I apply the hood and embroider the next track

I finish by embroidering the cover of the plaid part

I make the applique of the gnome's beard, I embroider the decorations inside and the position of the nose - I place on a piece of foam, I embroider the next trace and clipping the excess - I do the nose applique
I finish with the applique cover and embroidery the snowflake



I fix the hook on the left side of the sock
I take a rectangle of fabric measuring approximately 60x20 cm, fold it in half and inside
I insert the padding
I pin the sandwich over the sock and pin it, leaving the hood out
I embroider the last seam
I remove everything from the frame, cut out the shape and turn over
The sock is finished :)