

ITH-Candy-Cane-Gnomes-4x4-CF-NLS

Instructions



NLSEE2218-4x4
Stitch Count: 8,319
Size: 2.19 x 3.92 Inches

ITH-Candy-Cane-Gnomes-4x4-CF-NLS



NLSEE2219-4x4
Stitch Count: 8,001
Size: 2.20 x 3.91 Inches



NLSEE2220-4x4
Stitch Count: 6,226
Size: 2.26 x 3.87 Inches



NLSEE2221-4x4
Stitch Count: 6,960
Size: 3.28 x 3.88 Inches



NLSEE2222-4x4
Stitch Count: 8,841
Size: 2.89 x 3.83 inches


Materials/Cutting Chart

| Design Number | Materials | Number and Size of Cuts |
|----------------------|----------------------|--|
| NLSEE2218-4x4 | Felt (White) | 2 cuts at 4.5 x 2.5 inches |
| NLSEE2219-4x4 | Felt (White) | 2 cuts at 4.5 x 2.5 inches |
| NLSEE2220-4x4 | Felt (White) | 2 cuts at 4.5 x 2.5 inches |
| NLSEE2221-4x4 | Felt (White) | 2 cuts at 4 x 4 inches |
| NLSEE2222-4x4 | Felt (White) | 2 cuts at 3.5 x 4.25 inches |
| | Tear-Away-Stabilizer | Enough for a 4x4 inch embroidery hoop for each design |

NLSEE2222-4x4

The Color Sequence Chart below will be referenced throughout these instructions.

Color Sequence:



1. Prepare materials as indicated in Materials/Cutting Chart above. For these instructions, I will be stitching NLSEE2222-4x4.
2. Send the design to your embroidery machine.



3. Hoop tear-away stabilizer in your 4x4 inch embroider hoop and attach to machine.




4. Sew #1 in the Color Sequence Chart. These stitches will create the “**placement stitches**” for the gnome.



5. Remove hoop from machine, place right side up, on a flat surface.
6. Place one of the felt pieces over the “placement stitches” and secure with tape at top and bottom.

Tape



7. Return hoop to machine and sew #2 in the Color Sequence Chart. These stitches will attach the front, felt piece to the stabilizer.



8. Sew #3 in the Color Sequence Chart. These stitches will create the gnome’s nose.



9. Sew #4 in the Color Sequence Chart. These stitches will create the gnome's hat.



10. Sew #5 in the Color Sequence Chart. These stitches will create the white part of the Gnomes hat.

11. Sew #6 in the Color Sequence Chart. These stitches will create the gnome's shirt and dots on his hat.



12. Remove hoop from machine, place back-side-up on a flat surface and trim all thread tails.



Thread tails trimmed

13. While hoop is still on flat surface (back-side-up) place the second piece of felt over the back of the design. Make sure all areas are covered.
14. Return hoop to machine and sew #7 (red thread in needle and bobbin) and #8(White thread in needle and in bobbin) in the in the Color Sequence Chart. These stitches will attach the back, felt piece to the project.



15. Remove hoop from machine and project from hoop.
16. Cut away all stabilizer from around the gnome.



17. Using sharp scissors, carefully cut around the gnome, about 1/8 inch outside of the gnome-stitching.




18. Insert candy canes, bottom first through the provided arm-hole openings. Your Candy Cane Gnome is complete.



The **first two steps** and **last two steps** in the Color Sequence Charts are the same so they are sewn in similar fashion to the one outlined in the instructions.


NLSEE2118-4x4

Color Sequence:



NLSEE2219-4x4

Color Sequence:



NLSEE2220-4x4


Color Sequence:



Printed by Generations(TM), Copyright 2002-2007, All Rights Reserved.

NLSEE2221-4x4

Color Sequence:



Printed by Generations(TM), Copyright 2002-2007, All Rights Reserved.