ITH Halloween Welcome Gnome

The best ITH Halloween Welcome Gnome ever! ITH Halloween Welcome Gnome is made with fabric, just take all the work out of the project. Make these in less than 60 minutes.

Skill Level: Beginner **Time Required:** 01:00 hour.

Materials:

- 5" x 7" 6" x 10".
- Fabric in your favorite colors.
- 2.5-ounce Cut-away Stabilizer.
- Batting.
- Repositionable adhesive spray.
- Fabric scissors.

Designs used in this project:



Step 1:

For the Beard part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 2:

Cover the placement line with white fabric with the help of the repositionable adhesive spray, and run color-stops 3 and 4. Cut the excess fabric.



Step 3:

Run color-stop 5 as a placement line. Cover the placement line with khaki fabric with the help of the repositionable adhesive spray, and run color-stop 6. Cut the excess fabric.



Step 4: Run color-stop 7 through color-stop 10.



Step 5:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 11.



Step 6:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 7:

For the Wings part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 8:

Cover the placement line with black fabric with the help of the repositionable adhesive spray, and run color-stop 3. Cut the excess fabric. And run color-stop 4.



Step 9:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 5.



Step 10:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 11:

For the Shoes part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 12:

Cover the placement line with purple fabric with the help of the repositionable adhesive spray, and run color-stop 3. Cut the excess fabric. And run color-stops 4 and 5.



Step 13:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 6.



Step 14:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 15:

For the Plaque part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 16:

Cover the placement line with fabric with the help of the repositionable adhesive spray, and run color-stop 3. Cut the excess fabric. And run color-stops 4 and 5.



Step 17:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 6.



Step 18:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 19:

For the Hat part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 20:

Cover the placement line with black fabric with the help of the repositionable adhesive spray, and run color stops 3 and 4. Cut the excess fabric.



Step 21:

Run color-stop 5 as a placement line. Cover the placement line with gray fabric with the help of the repositionable adhesive spray, and run color-stop 6. Cut the excess fabric.



Step 22: Run color-stop 7 through color-stop 9.



Step 23:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 10.



Step 24:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 25:

For the Hands part tautly hoop 2.5-ounce cutaway stabilizer in your embroidery hoop and run color-stop 1 as a placement line.

Remove the hoop from the machine, do not unhoop. Cover the placement line with batting with the help of the repositionable adhesive spray, and run color-stop 2.



Step 26:

Cover the placement line with khaki fabric with the help of the repositionable adhesive spray, and run color-stop 3. Cut the excess fabric. And run color-stop 4.



Step 27:

Remove the hoop from the machine, do not unhoop. Cover the back of the hoop with white fabric with the help of the repositionable adhesive spray and run color-stop 5.



Step 28:

Remove the project from the hoop. Cut out the outline of the design, with sharp scissors, and save it for later.



Step 29:

We put all the pieces together.



Step 30:

With the help of a needle and thread or some type of textile glue, The Beard part will be the lower center part, join the shoes to the beard and then join the wings at the height you prefer in the back part of the beard. Join the hat and finally join the plaque part to the rest of the project.

P.S.: Don't forget to open the little holes in the Wings and the Plaque, that way un can tie up the ribbons.

Use complementary decoration.

Have fun doing this beautiful project.

